

Joining methods


Thermofix

Cut to dimensions

Skive

Apply adhesive

Hot-pressing




Flexproof

Cut to dimensions

Die-cut/Finger-cut

Joining

Hot-pressing



Quickmelt

Cut to dimensions and angle

Joining

Hot-pressing

